d his

(FILE 'HOME' ENTERED AT 16:15:52 ON 12 DEC 2001)

L1		STRY' ENTERED AT 16:16:01 ON 12 DEC 2001 (.8 <fe<3 .3<ni<2="" .5<sn<2="" 0<p<.5="" 50<cu)="" and="" mac<="" td=""></fe<3>
L2	33	(.8 <fe<3 .3<ni<2="" .5<sn<2="" 0<p<.5="" 50<cu)="" and="" mac<="" td=""></fe<3>
	FILE 'HCA'	ENTERED AT 16:17:54 ON 12 DEC 2001
L3	25	L2
L4	5227	(NICKEL OR NI) AND (COPPER OR CU) AND (IRON OR FE) AND (TIN OR
L5	21	L3 AND L4
		SELECT L5 IPC 1-2 4 16 18
Lб	132261	E1-7
L7	78046	(COPPER OR CU) (1A) (ALLOY OR BASE? OR REMAIN? OR BALANC?)
L8	540	L7 AND L4 AND L6
L9	9	L8 AND IACS AND YIELD